

CERTIFICATE OF CONFORMANCE
FOR
MATERIALS SHIPPED

Tulsa Gas Technologies, Inc. (TGT) hereby certifies that all materials in the manufacture of hoses on SN 24061465 JWPC material and/or manufacturing specifications indicated in drawings, bulletins or specifications as called for on the said purchase order. Test reports are on file with us or with our suppliers for examination and indicate conformance with applicable specification requirements. In production items listed, no direct contact was made with mercury, any of its compounds or with any mercury containing devices employing a single boundary for containment. Tulsa Gas Technologies, Inc. also certifies that the parts listed and shipped on the date indicated are manufactured in accordance with Parker specifications and quality standards, if applicable, as stated on the drawings or specifications called for on said purchase order. All parts and test conform to AGA I-93.

SIGNED BY: Patrick McElhenny
TITLE: Hose Assembler
DATE: 6-27-24

Tulsa Gas Technologies, Inc.
4309 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

AVEN122223
Spring Creek Bus Depot
18895
6-3-24

ASSEMBLY/CERTIFICATION SHEET

		SIGN	DATE						
1	☒ Review shop work order versus customer print and history	PM	6-27-24						
2	☒ Component part numbers: <u>106CG1-12-12, 106CG1-12-12</u>								
	Pack dates and/or QC codes	PM	6-27-24						
3	☒ ID band number <u>5CNG12/5CNG16-0606/0606-1212/66-36"</u>	PM	6-27-24						
4	☒ Hose Cut Length <u>36"</u>	PM	6-27-24						
5	☐ Pre-expansion of hose (if required) Size								
	Remarks:								
6	☒ Audit and mark appropriate insertion depth	PM	6-27-24						
7	☐ Add special accessories								
	Remarks:								
8	☒ Apply danger tag and ID band	PM	6-27-24						
9	☒ Install bend restrictors	PM	6-27-24						
	Remarks:								
10	☒ Assemble fittings; check insertion depth	PM	6-27-24						
	Remarks:								
11	☐ Set offset angle and/or orientation								
	Remarks:								
12	☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58								
	<table border="0"><tr><td>☐ 1/2) 80C-PO8H</td><td>☐ 3/8) 80C-PO6H</td></tr><tr><td>☐ 1/4) 80C-PO4H</td><td>☐ 1/8) 80C-PO2</td></tr><tr><td>☐ 3/8) 80C-PO6</td><td>☒ 3/4) 80C-P12H</td></tr></table>	☐ 1/2) 80C-PO8H	☐ 3/8) 80C-PO6H	☐ 1/4) 80C-PO4H	☐ 1/8) 80C-PO2	☐ 3/8) 80C-PO6	☒ 3/4) 80C-P12H	PM	6-27-24
☐ 1/2) 80C-PO8H	☐ 3/8) 80C-PO6H								
☐ 1/4) 80C-PO4H	☐ 1/8) 80C-PO2								
☐ 3/8) 80C-PO6	☒ 3/4) 80C-P12H								
13	☐ Add special accessories after crimping/swaging								
14	☐ Perform and record burst test results, if applicable								
	Remarks:								
15	☐ Air test, if applicable								
	Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One)								
	Remarks:								
16	☒ Hydrostatic proof test								
	Test pressure Psi <u>10,000</u> Seconds <u>30</u> (Pass/Fail (Circle One))								
	Remarks:	PM	6-27-24						
17	☒ Flush method water, and then air	PM	6-27-24						
18	☒ Perform and record conductivity test; Meter <u>Megger Mit200</u>								
	Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u>								
	(=) Final hose resistance <u>0.03</u>	PM	6-27-24						
19	☒ Final audit: Check boxes for items inspected, as applicable:								
	☒ Correct hose; ☒ Correct fittings; ☒ Correct customer PN	PM	6-27-24						
20	☒ Check swage or crimp diameters:								
	<table border="0"><tr><td><u>5CNG-6-58 .785/.805</u></td><td><u>5CNG-8-58 .900/.920</u></td></tr><tr><td><u>5CNG-6-55 .675/.695</u></td><td><u>5CNG-12-58 1.20/1.22</u></td></tr></table>	<u>5CNG-6-58 .785/.805</u>	<u>5CNG-8-58 .900/.920</u>	<u>5CNG-6-55 .675/.695</u>	<u>5CNG-12-58 1.20/1.22</u>	PM	6-27-24		
<u>5CNG-6-58 .785/.805</u>	<u>5CNG-8-58 .900/.920</u>								
<u>5CNG-6-55 .675/.695</u>	<u>5CNG-12-58 1.20/1.22</u>								
	*****100% VISUAL INSPECT FOR THE FOLLOWING*****								
21	☒ Hose fittings crimped; ☒ Air passes through assembly;								
	☒ Presence of threads	PM	6-27-24						
20	☒ Cap and package hose	PM	6-27-24						
21	☐ Certificate of Conformance for Materials Shipped (on back)								


X-1

- 3 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 7 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"

- 1 58 SERIES
HOSE SIZE
4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

- 4 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 8 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"

Cut 36"
11 FILL HOSE LENGTH
36"



- 5 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 9 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"

- 2 55 SERIES
HOSE SIZE
2 1/8"
4 1/4"
6 3/8"

- 6 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 10 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"

STANDARD 3"
SHEREX 5/8"

WORK ORDER #

1 5CNG 2 3 4 5 6 7 8 9 10 11
6 06 06 05 06 12 12 16 6 - 36"

Tulsa Gas Technologies, Inc.
4809 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

AVEN122223
Spring Creek Bus Depot
1889
6-3-24

ASSEMBLY/CERTIFICATION SHEET

		SIGN	DATE										
1	☒ Review shop work order versus customer print and history	PM	6-27-24										
2	☒ Component part numbers: <u>106CG-12-12, 106CG-12-12</u>												
	Pack dates and/or QC codes	PM	6-27-24										
3	☒ ID band number <u>5CNG12/5CNG16-0606/0506-1212/66-96"</u>	PM	6-27-24										
4	☒ Hose Cut Length <u>96"</u>	PM	6-27-24										
5	☐ Pre-expansion of hose (if required) Size _____												
	Remarks: _____												
6	☒ Audit and mark appropriate insertion depth	PM	6-27-24										
7	☐ Add special accessories _____												
	Remarks: _____												
8	☒ Apply danger tag and ID band	PM	6-27-24										
9	☒ Install bend restrictors	PM	6-27-24										
	Remarks: _____												
10	☒ Assemble fittings; check insertion depth	PM	6-27-24										
	Remarks: _____	PM	6-27-24										
11	☐ Set offset angle and/or orientation												
	Remarks: _____												
12	☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58												
	<table border="0"><tr><td>☐ 1/2) 80C-PO8H</td><td>☐ 3/8) 80C-PO6H</td></tr><tr><td>☐ 1/4) 80C-PO4H</td><td>☐ 1/8) 80C-PO2</td></tr><tr><td>☐ 3/8) 80C-PO6</td><td>☒ 3/4) 80C-P12H</td></tr></table>	☐ 1/2) 80C-PO8H	☐ 3/8) 80C-PO6H	☐ 1/4) 80C-PO4H	☐ 1/8) 80C-PO2	☐ 3/8) 80C-PO6	☒ 3/4) 80C-P12H	PM	6-27-24				
☐ 1/2) 80C-PO8H	☐ 3/8) 80C-PO6H												
☐ 1/4) 80C-PO4H	☐ 1/8) 80C-PO2												
☐ 3/8) 80C-PO6	☒ 3/4) 80C-P12H												
13	☐ Add special accessories after crimping/swaging												
14	☐ Perform and record burst test results, if applicable												
	Remarks: _____												
15	☐ Air test, if applicable												
	Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One)												
	Remarks: _____												
16	☒ Hydrostatic proof test												
	Test pressure Psi <u>10,000</u> Seconds <u>30</u> ; <u>Pass</u> /Fail (Circle One)												
	Remarks: _____	PM	6-27-24										
17	☒ Flush method water, and then air	PM	6-27-24										
18	☒ Perform and record conductivity test; Meter _____ Megger Mit200												
	Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u>												
	(=) Final hose resistance <u>0.03</u>	PM	6-27-24										
19	☒ Final audit: Check boxes for items inspected, as applicable:												
	☒ Correct hose; ☒ Correct fittings; ☒ Correct customer PN	PM	6-27-24										
20	☒ Check swage or crimp diameters: <table border="0"><tr><td><u>5CNG-4-58 .668/.688</u></td><td>☐</td></tr><tr><td><u>5CNG-6-58 .785/.805</u></td><td>☐</td></tr><tr><td><u>5CNG-6-55 .675/.695</u></td><td>☒</td></tr><tr><td><u>5CNG-8-58 .900/.920</u></td><td>☐</td></tr><tr><td><u>5CNG-12-58 1.20/1.22</u></td><td>☐</td></tr></table>	<u>5CNG-4-58 .668/.688</u>	☐	<u>5CNG-6-58 .785/.805</u>	☐	<u>5CNG-6-55 .675/.695</u>	☒	<u>5CNG-8-58 .900/.920</u>	☐	<u>5CNG-12-58 1.20/1.22</u>	☐	PM	6-27-24
<u>5CNG-4-58 .668/.688</u>	☐												
<u>5CNG-6-58 .785/.805</u>	☐												
<u>5CNG-6-55 .675/.695</u>	☒												
<u>5CNG-8-58 .900/.920</u>	☐												
<u>5CNG-12-58 1.20/1.22</u>	☐												
	*****100% VISUAL INSPECT FOR THE FOLLOWING*****												
21	☒ Hose fittings crimped; ☒ Air passes through assembly;												
	☒ Presence of threads	PM	6-27-24										
20	☒ Cap and package hose	PM	6-27-24										
21	☐ Certificate of Conformance for Materials Shipped (on back)												

X4

- 3 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 7 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"
- 06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL


- 1 58 SERIES
HOSE SIZE
4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

- 4 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 8 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"
- 06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

Cut 105"

11 FILL HOSE LENGTH
96"

BREAK-AWAY END



FILL END

- 5 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 9 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"
- 05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

- 2 55 SERIES
HOSE SIZE
2 1/8"
4 1/4"
6 3/8"

- 6 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 10 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"
- 06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

STANDARD 3" SHEREX 5/8" 5/8"

WORK ORDER #

5CNG12/5CNG12-0606/0506-1212/66-96"

FILL HOSE	
DATE: 03/27/87	DESIGNED BY: C. SEWELL
DRAWN BY: C.R.S.	CHECKED BY: NONE
DWG. NO. FILLHOSE WORKORDR.002	SHEET NO. OF 1

TULSA GAS TECHNOLOGIES, INC.
10117 EAST 40TH STREET
TULSA, OK 74119
918-882-2941 FAX: 918-882-2957

Tulsa Gas Technologies, Inc.
4809 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

AVEN122223
Spring Creek Bus Depot
1880P
6-3-24

ASSEMBLY/CERTIFICATION SHEET

		SIGN	DATE
1	☒ Review shop work order versus customer print and history	PM	6-27-24
2	☒ Component part numbers: <u>106CG-12-12, 106CG-12-12</u>		
	Pack dates and/or QC codes	PM	6-27-24
3	☒ ID band number <u>5CNG12/5CNG16-0606/0506-1212/66-36"</u>	PM	6-27-24
4	☒ Hose Cut Length <u>36"</u>	PM	6-27-24
5	Pre-expansion of hose (if required) Size		
	Remarks:		
6	☒ Audit and mark appropriate insertion depth	PM	6-27-24
7	Add special accessories		
	Remarks:		
8	☒ Apply danger tag and ID band	PM	6-27-24
9	☒ Install bend restrictors	PM	6-27-24
	Remarks:		
10	☒ Assemble fittings; check insertion depth	PM	6-27-24
	Remarks:		
11	Set offset angle and/or orientation		
	Remarks:		
12	☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58		
	<u>1/2) 80C-PO8H</u> <u>3/8) 80C-PO6H</u>		
	<u>1/4) 80C-PO4H</u> <u>1/8) 80C-PO2</u>		
	<u>3/8) 80C-PO6</u> <u>3/4) 80C-P12H</u>	PM	6-27-24
13	Add special accessories after crimping/swaging		
14	Perform and record burst test results, if applicable		
	Remarks:		
15	Air test, if applicable		
	Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One)		
	Remarks:		
16	☒ Hydrostatic proof test		
	Test pressure Psi <u>10,000</u> Seconds <u>30</u> ; Pass/Fail (Circle One)		
	Remarks:	PM	6-27-24
17	☒ Flush method water, and then air	PM	6-27-24
18	☒ Perform and record conductivity test; Meter <u>Megger Mit200</u>		
	Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u>		
	(=) Final hose resistance <u>0.03</u>	PM	6-27-24
19	☒ Final audit: Check boxes for items inspected, as applicable:		
	☒ Correct hose; ☒ Correct fittings; ☒ Correct customer PN	PM	6-27-24
20	☒ Check swage or crimp diameters:		
	<u>5CNG-4-58 .668/.688</u>		
	<u>5CNG-6-58 .785/.805</u> <u>5CNG-8-58 .900/.920</u>	PM	6-27-24
	<u>5CNG-6-55 .675/.695</u> <u>5CNG-12-58 1.20/1.22</u>		
	*****100% VISUAL INSPECT FOR THE FOLLOWING*****		
21	☒ Hose fittings crimped; ☒ Air passes through assembly;		
	☒ Presence of threads	PM	6-27-24
20	☒ Cap and package hose	PM	6-27-24
21	Certificate of Conformance for Materials Shipped (on back)		


X-1

- 3 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 7 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"
- 06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

- 1 58 SERIES
HOSE SIZE
4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

- 4 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 8 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"
- 06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

Cut 36"
11 FILL HOSE LENGTH
36"



- 5 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 9 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"
- 05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

- 2 55 SERIES
HOSE SIZE
2 1/8"
4 1/4"
6 3/8"

- 6 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 10 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"
- 06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

STANDARD 3"
SHEREX 5/8"

WORK ORDER #

5CNG1/5CNG6-0606/0506-1212/66-36"

FILL HOSE	
DATE: 03/27/87	TULSA GAS TECHNOLOGIES, INC.
DESIGNED BY: C. SEWELL	1501 TULSA AVE. STREET
DRAWN BY: C.R.S.	TULSA, OK 74119
DWG. NO. FILLHOSE worlorder.dwg	918-845-2841 FAX: 918-845-2827
SHEET NO. 2	SCALE: NONE
OF	REV. 1

Tulsa Gas Technologies, Inc.
4809 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

AVEN122223
Spring Creek Bus Depot
1889
6-3-24

ASSEMBLY/CERTIFICATION SHEET

		SIGN	DATE						
1	☒ Review shop work order versus customer print and history	PM	6-27-24						
2	☒ Component part numbers: <u>106CG-12-12, 106CG-12-12</u> Pack dates and/or QC codes	PM	6-27-24						
3	☒ ID band number <u>5CNG12/5CNG6-0606/0506-1212/66-96"</u>	PM	6-27-24						
4	☒ Hose Cut Length <u>96"</u>	PM	6-27-24						
5	☐ Pre-expansion of hose (if required) Size _____ Remarks: _____								
6	☒ Audit and mark appropriate insertion depth	PM	6-27-24						
7	☐ Add special accessories _____ Remarks: _____								
8	☒ Apply danger tag and ID band	PM	6-27-24						
9	☒ Install bend restrictors Remarks: _____	PM	6-27-24						
10	☒ Assemble fittings; check insertion depth Remarks: _____	PM	6-27-24						
11	☐ Set offset angle and/or orientation Remarks: _____								
12	☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58 <table border="0" style="width: 100%;"><tr><td>_____ 1/2) 80C-PO8H</td><td>_____ 3/8) 80C-PO6H</td></tr><tr><td>_____ 1/4) 80C-PO4H</td><td>_____ 1/8) 80C-PO2</td></tr><tr><td>_____ 3/8) 80C-PO6</td><td><u>J</u> 3/4) 80C-P12H</td></tr></table>	_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H	_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2	_____ 3/8) 80C-PO6	<u>J</u> 3/4) 80C-P12H	PM	6-27-24
_____ 1/2) 80C-PO8H	_____ 3/8) 80C-PO6H								
_____ 1/4) 80C-PO4H	_____ 1/8) 80C-PO2								
_____ 3/8) 80C-PO6	<u>J</u> 3/4) 80C-P12H								
13	☐ Add special accessories after crimping/swaging								
14	☐ Perform and record burst test results, if applicable Remarks: _____								
15	☐ Air test, if applicable Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One) Remarks: _____								
16	☒ Hydrostatic proof test Test pressure Psi <u>10,000</u> Seconds <u>30</u> ; <u>Pass</u> /Fail (Circle One) Remarks: _____	PM	6-27-24						
17	☒ Flush method water, and then air	PM	6-27-24						
18	☒ Perform and record conductivity test; Meter _____ Megger Mit200 Hose resistance <u>0.01</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	PM	6-27-24						
19	☒ Final audit: Check boxes for items inspected, as applicable: <table border="0" style="width: 100%;"><tr><td>☒ Correct hose;</td><td>☒ Correct fittings;</td><td>☒ Correct customer PN</td></tr></table>	☒ Correct hose;	☒ Correct fittings;	☒ Correct customer PN	PM	6-27-24			
☒ Correct hose;	☒ Correct fittings;	☒ Correct customer PN							
20	☒ Check swage or crimp diameters: _____ <table border="0" style="width: 100%;"><tr><td>5CNG-4-58 .668/.688</td><td>_____</td></tr><tr><td>5CNG-6-58 .785/.805</td><td>_____</td></tr><tr><td>5CNG-6-55 .675/.695</td><td><u>J</u> 5CNG-12-58 1.20/1.22</td></tr></table>	5CNG-4-58 .668/.688	_____	5CNG-6-58 .785/.805	_____	5CNG-6-55 .675/.695	<u>J</u> 5CNG-12-58 1.20/1.22	PM	6-27-24
5CNG-4-58 .668/.688	_____								
5CNG-6-58 .785/.805	_____								
5CNG-6-55 .675/.695	<u>J</u> 5CNG-12-58 1.20/1.22								
*****100% VISUAL INSPECT FOR THE FOLLOWING*****									
21	☒ Hose fittings crimped; ☒ Air passes through assembly;								
	☒ Presence of threads	PM	6-27-24						
20	☒ Cap and package hose	PM	6-27-24						
21	☐ Certificate of Conformance for Materials Shipped (on back)								


X 64

- 3 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 7 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"
- 11 FILL HOSE LENGTH
9 1/6"

- 1 58 SERIES
HOSE SIZE
4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

- 4 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 8 FITTING SIZE
4 1/4"
6 3/8"
8 1/2"
12 3/4"

BREAK-AWAY END



- 5 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 9 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"

- 2 55 SERIES
HOSE SIZE
2 1/8"
4 1/4"
6 3/8"

- 6 FITTING TYPE
01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL
- 10 FITTING SIZE
2 1/8"
4 1/4"
6 3/8"

WORK ORDER #

5CNG12/5CNG12-0606/0506-1212/66-96"

FILL HOSE	
DATE: 03/27/07	DESIGNED BY: C. SEWELL
DRAWN BY: C.R.S.	CHECKED BY: NONE
DWG. NO. FILLHOSE worlorder.dwg	SHEET NO. OF 1

TULSA GAS TECHNOLOGIES, INC.
10117 EAST 41TH STREET
TULSA, OK 74116
918-485-2841 FAX: 918-485-2857