

CERTIFICATE OF CONFORMANCE
FOR
MATERIALS SHIPPED

Tulsa Gas Technologies, Inc. (TGT) hereby certifies that all materials in the manufacture of hoses for W/O # JWPC041224 conform to the manufacturing specifications indicated in drawings, bulletins or specifications as called for on the said purchase order. Test reports are on file with us or with our suppliers for examination and indicate conformance with applicable specification requirements. In production items listed, no direct contact was made with mercury, any of its compounds or with any mercury containing devices employing a single boundary for containment. Tulsa Gas Technologies, Inc. also certifies that the parts listed and shipped on the date indicated are manufactured in accordance with Parker specifications and quality standards, if applicable, as stated on the drawings or specifications called for on said purchase order. All parts and test conform to AGA I-93.

SIGNED BY: Patrick McElherney
TITLE: Hose Builder
DATE: 12-19-24

Tulsa Gas Technologies, Inc.
4809 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

JW PC 041224
JW Power Co.
P1343278
4-12-24

ASSEMBLY/CERTIFICATION SHEET

		SIGN	DATE
1	☒ Review shop work order versus customer print and history	PM	12-19-24
2	☒ Component part numbers: <u>106CG-8-8, 106CG-8-8</u> Pack dates and/or QC codes	PM	12-19-24
3	☒ ID band number <u>5205104731</u>	PM	12-19-24
4	☒ Hose Cut Length <u>96"</u>	PM	12-19-24
5	Pre-expansion of hose (if required) Size _____ Remarks: _____		
6	☒ Audit and mark appropriate insertion depth	PM	12-19-24
7	Add special accessories _____ Remarks: _____		
8	☒ Apply danger tag and ID band	PM	12-19-24
9	☒ Install bend restrictors Remarks: _____	PM	12-19-24
10	☒ Assemble fittings; check insertion depth Remarks: _____	PM	12-19-24
11	Set offset angle and/or orientation Remarks: _____		
12	☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58 <u>1/2</u> 80C-PO8H <u>1/4</u> 80C-PO4H <u>3/8</u> 80C-PO6 <u>3/8</u> 80C-PO6H <u>1/8</u> 80C-PO2 <u>3/4</u> 80C-P12H	PM	12-19-24
13	Add special accessories after crimping/swaging		
14	Perform and record burst test results, if applicable Remarks: _____		
15	Air test, if applicable Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One) Remarks: _____		
16	☒ Hydrostatic proof test Test pressure Psi <u>10,000</u> Seconds <u>30</u> <u>Pass</u> Fail (Circle One) Remarks: _____	PM	12-19-24
17	☒ Flush method water, and then air	PM	12-19-24
18	☒ Perform and record conductivity test; Meter <u>Megger Mit200</u> Hose resistance <u>0.02</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	PM	12-19-24
19	☒ Final audit: Check boxes for items inspected, as applicable: ☒ Correct hose; ☒ Correct fittings; ☒ Correct customer PN	PM	12-19-24
20	☒ Check swage or crimp diameters: <u>5CNG-6-58 .785/.805</u> <u>5CNG-6-55 .675/.695</u> ☒ <u>5CNG-8-58 .900/.920</u> <u>5CNG-12-58 1.20/1.22</u>	PM	12-19-24
*****100% VISUAL INSPECT FOR THE FOLLOWING*****			
21	☒ Hose fittings crimped; ☒ Presence of threads	PM	12-19-24
20	☒ Cap and package hose	PM	12-19-24
21	☒ Certificate of Conformance for Materials Shipped (on back)	PM	12-19-24

Tulsa Gas Technologies, Inc.
4809 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

JWPC041224
JW Power CO.
P1343278
4-12-24

ASSEMBLY/CERTIFICATION SHEET

- | | | SIGN | DATE | | | | | | |
|---|--|--|--|--|--|--|---|----|----------|
| 1 | ☒ Review shop work order versus customer print and history | PM | 12-19-24 | | | | | | |
| 2 | ☒ Component part numbers: <u>106CG-12-12, 106CG-12-12</u>
Pack dates and/or QC codes | PM | 12-19-24 | | | | | | |
| 3 | ☒ ID band number <u>522/324220</u> | PM | 12-19-24 | | | | | | |
| 4 | ☒ Hose Cut Length <u>36"</u> | PM | 12-19-24 | | | | | | |
| 5 | ☐ Pre-expansion of hose (if required) Size _____
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 6 | ☒ Audit and mark appropriate insertion depth | PM | 12-19-24 | | | | | | |
| 7 | ☐ Add special accessories _____
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 8 | ☒ Apply danger tag and ID band | PM | 12-19-24 | | | | | | |
| 9 | ☒ Install bend restrictors _____
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 10 | ☒ Assemble fittings; check insertion depth _____
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 11 | ☐ Set offset angle and/or orientation _____
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 12 | ☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58
<table border="0"><tr><td>☐ 1/2) 80C-PO8H</td><td>☐ 3/8) 80C-PO6H</td></tr><tr><td>☐ 1/4) 80C-PO4H</td><td>☒ 1/8) 80C-PO2</td></tr><tr><td>☐ 3/8) 80C-PO6</td><td>☒ 3/4) 80C-P12H</td></tr></table> | ☐ 1/2) 80C-PO8H | ☐ 3/8) 80C-PO6H | ☐ 1/4) 80C-PO4H | ☒ 1/8) 80C-PO2 | ☐ 3/8) 80C-PO6 | ☒ 3/4) 80C-P12H | PM | 12-19-24 |
| ☐ 1/2) 80C-PO8H | ☐ 3/8) 80C-PO6H | | | | | | | | |
| ☐ 1/4) 80C-PO4H | ☒ 1/8) 80C-PO2 | | | | | | | | |
| ☐ 3/8) 80C-PO6 | ☒ 3/4) 80C-P12H | | | | | | | | |
| 13 | ☐ Add special accessories after crimping/swaging | | | | | | | | |
| 14 | ☐ Perform and record burst test results, if applicable
Remarks: _____ | | | | | | | | |
| 15 | ☐ Air test, if applicable
Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One)
Remarks: _____ | | | | | | | | |
| 16 | ☒ Hydrostatic proof test
Test pressure Psi <u>10,000</u> Seconds <u>30</u> (<u>Pass</u>) Fail (Circle One)
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 17 | ☒ Flush method water, and then air | PM | 12-19-24 | | | | | | |
| 18 | ☒ Perform and record conductivity test; Meter <u>Megger Mit200</u>
Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u>
(=) Final hose resistance <u>0.03</u> | PM | 12-19-24 | | | | | | |
| 19 | ☒ Final audit: Check boxes for items inspected, as applicable:
☒ Correct hose; ☒ Correct fittings; ☒ Correct customer PN | PM | 12-19-24 | | | | | | |
| 20 | ☒ Check swage or crimp diameters:
<table border="0"><tr><td>☐ 5CNG-4-58 .668/.688</td><td>☐ 5CNG-8-58 .900/.920</td></tr><tr><td>☐ 5CNG-6-58 .785/.805</td><td>☐ 5CNG-12-58 1.20/1.22</td></tr><tr><td>☐ 5CNG-6-55 .675/.695</td><td>☒</td></tr></table> | ☐ 5CNG-4-58 .668/.688 | ☐ 5CNG-8-58 .900/.920 | ☐ 5CNG-6-58 .785/.805 | ☐ 5CNG-12-58 1.20/1.22 | ☐ 5CNG-6-55 .675/.695 | ☒ | PM | 12-19-24 |
| ☐ 5CNG-4-58 .668/.688 | ☐ 5CNG-8-58 .900/.920 | | | | | | | | |
| ☐ 5CNG-6-58 .785/.805 | ☐ 5CNG-12-58 1.20/1.22 | | | | | | | | |
| ☐ 5CNG-6-55 .675/.695 | ☒ | | | | | | | | |
| *****100% VISUAL INSPECT FOR THE FOLLOWING***** | | | | | | | | | |
| 21 | ☒ Hose fittings crimped; ☒ Air passes through assembly;
☒ Presence of threads | PM | 12-19-24 | | | | | | |
| 20 | ☒ Cap and package hose | PM | 12-19-24 | | | | | | |
| 21 | ☒ Certificate of Conformance for Materials Shipped (on back) | PM | 12-19-24 | | | | | | |

3

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

7

FITTING SIZE

- 4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

1

CG SERIES
HOSE SIZE

- 4 1/4"
6 3/8"
8 1/2"
12 3/4"

4

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

8

FITTING SIZE


- 4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

BREAK-AWAY OR
DISPENSER END

cat 105"

11 FILL HOSE LENGTH
96"

FILL END



5

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

9

FITTING SIZE

- 2 1/8"
4 1/4"
6 3/8"

2

CG SERIES

- HOSE SIZE
4 1/4"
6 3/8"

6

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

10

FITTING SIZE

- 2 1/8"
4 1/4"
6 3/8"

SHEREX CT1000 use 1/4" VENT ONLY 5/8"
SHEREX CT5000 use 3/8" VENT ONLY

WORK ORDER # 3wpc041224

5CNG 8/5CNG 4-06 06/05 06-88/64-96"

FILL HOSE

TULSA GAS TECHNOLOGIES, INC.
10117 EAST 48TH STREET
TULSA, OK 74146

DATE: 03/27/97

DESIGNED BY: G. SEVELL

CHECKED BY: []

DRAWN BY: G.R.S.

SCALE: NTF

3

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

7

FITTING SIZE

- 4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

1

CG SERIES
HOSE SIZE

- 4 1/4"
6 3/8"
8 1/2"
12 3/4"

4

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL


8

FITTING SIZE

- 4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

BREAK-AWAY OR
DISPENSER END11 FILL HOSE LENGTH
36"

FILL END



5

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

9

FITTING SIZE

- 2 1/8"
4 1/4"
6 3/8"

2

CG SERIES
HOSE SIZE

- 4 1/4"
6 3/8"

6

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

10

FITTING SIZE

- 2 1/8"
4 1/4"
6 3/8"

SHEREX CT1000 use 1/4" VENT ONLY 5/8" VENT ONLY
SHEREX CT5000 use 3/8" VENT ONLY

WORK ORDER # JWP 041224

1 2 3 4 5 6 7 8 9 10 11
5CNG 8/5CNG 4-06 06 / 05 06 -88/64-36"

FILL HOSE

TULSA GAS TECHNOLOGIES, INC.
10117 EAST 48TH STREET
TULSA, OK 74146
DATE: 03/27/97 018-605-2841 FAX: 018-605-2057
DESIGNED BY: C. SEWELL CHECKED BY:
DRAWN BY: C.R.S. RCAL F. NONE

Tulsa Gas Technologies, Inc.
4809 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

JWPC041224
JW Power CO.
P1343278
4-12-24

ASSEMBLY/CERTIFICATION SHEET

- | | | SIGN | DATE | | | | | | |
|---|---|---------------------|---------------------|---------------------|----------------------|---------------------|---------------|----|----------|
| 1 | ☒ Review shop work order versus customer print and history | PM | 12-19-24 | | | | | | |
| 2 | ☒ Component part numbers: <u>106CG-12-12, 106CG-12-12</u>
Pack dates and/or QC codes | PM | 12-19-24 | | | | | | |
| 3 | ☒ ID band number <u>5221324219</u> | PM | 12-19-24 | | | | | | |
| 4 | ☒ Hose Cut Length <u>96"</u> | PM | 12-19-24 | | | | | | |
| 5 | Pre-expansion of hose (if required) Size _____
Remarks: _____ | | | | | | | | |
| 6 | ☒ Audit and mark appropriate insertion depth | PM | 12-19-24 | | | | | | |
| 7 | Add special accessories _____
Remarks: _____ | | | | | | | | |
| 8 | ☒ Apply danger tag and ID band | PM | 12-19-24 | | | | | | |
| 9 | ☒ Install bend restrictors
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 10 | ☒ Assemble fittings; check insertion depth
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 11 | Set offset angle and/or orientation
Remarks: _____ | | | | | | | | |
| 12 | ☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58
<table border="0" style="width: 100%;"><tr><td>1/2) 80C-PO8H</td><td>3/8) 80C-PO6H</td></tr><tr><td>1/4) 80C-PO4H</td><td>1/8) 80C-PO2</td></tr><tr><td>3/8) 80C-PO6</td><td>3/4) 80C-P12H</td></tr></table> | 1/2) 80C-PO8H | 3/8) 80C-PO6H | 1/4) 80C-PO4H | 1/8) 80C-PO2 | 3/8) 80C-PO6 | 3/4) 80C-P12H | PM | 12-19-24 |
| 1/2) 80C-PO8H | 3/8) 80C-PO6H | | | | | | | | |
| 1/4) 80C-PO4H | 1/8) 80C-PO2 | | | | | | | | |
| 3/8) 80C-PO6 | 3/4) 80C-P12H | | | | | | | | |
| 13 | Add special accessories after crimping/swaging | | | | | | | | |
| 14 | Perform and record burst test results, if applicable
Remarks: _____ | | | | | | | | |
| 15 | Air test, if applicable
Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One)
Remarks: _____ | | | | | | | | |
| 16 | ☒ Hydrostatic proof test
Test pressure Psi <u>10,000</u> Seconds <u>30</u> <u>(Pass)</u> Fail (Circle One)
Remarks: _____ | PM | 12-19-24 | | | | | | |
| 17 | ☒ Flush method water, and then air | PM | 12-19-24 | | | | | | |
| 18 | ☒ Perform and record conductivity test; Meter <u>Megger Mit200</u>
Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u>
(=) Final hose resistance <u>0.03</u> | PM | 12-19-24 | | | | | | |
| 19 | ☒ Final audit: Check boxes for items inspected, as applicable:
☒ Correct hose; ☒ Correct fittings; ☒ Correct customer PN | PM | 12-19-24 | | | | | | |
| 20 | ☒ Check swage or crimp diameters:
<table border="0" style="width: 100%;"><tr><td>5CNG-4-58 .668/.688</td><td>5CNG-8-58 .900/.920</td></tr><tr><td>5CNG-6-58 .785/.805</td><td>5CNG-12-58 1.20/1.22</td></tr><tr><td>5CNG-6-55 .675/.695</td><td></td></tr></table> | 5CNG-4-58 .668/.688 | 5CNG-8-58 .900/.920 | 5CNG-6-58 .785/.805 | 5CNG-12-58 1.20/1.22 | 5CNG-6-55 .675/.695 | | PM | 12-19-24 |
| 5CNG-4-58 .668/.688 | 5CNG-8-58 .900/.920 | | | | | | | | |
| 5CNG-6-58 .785/.805 | 5CNG-12-58 1.20/1.22 | | | | | | | | |
| 5CNG-6-55 .675/.695 | | | | | | | | | |
| *****100% VISUAL INSPECT FOR THE FOLLOWING***** | | | | | | | | | |
| 21 | ☒ Hose fittings crimped;
☒ Presence of threads | PM | 12-19-24 | | | | | | |
| 22 | Air passes through assembly; | PM | 12-19-24 | | | | | | |
| 20 | ☒ Cap and package hose | PM | 12-19-24 | | | | | | |
| 21 | ☒ Certificate of Conformance for Materials Shipped (on back) | PM | 12-19-24 | | | | | | |

Tulsa Gas Technologies, Inc.
4809 S. 101st. E. Ave.
Tulsa, OK 74146
918-665-2641

Work Order #
Customer Name
Customer PO
Date Required

JWPC091224
JW Power CO.
P1348278
4-12-24

ASSEMBLY/CERTIFICATION SHEET

		SIGN	DATE
1	☒ Review shop work order versus customer print and history	PM	12-19-24
2	☒ Component part numbers: <u>106CG-8-8, 106CG-8-8</u> Pack dates and/or QC codes	PM	12-19-24
3	☒ ID band number <u>5205104731</u>	PM	12-19-24
4	☒ Hose Cut Length <u>36"</u>	PM	12-19-24
5	Pre-expansion of hose (if required) Size _____ Remarks: _____	PM	12-19-24
6	☒ Audit and mark appropriate insertion depth	PM	12-19-24
7	Add special accessories _____ Remarks: _____	PM	12-19-24
8	☒ Apply danger tag and ID band	PM	12-19-24
9	☒ Install bend restrictors Remarks: _____	PM	12-19-24
10	☒ Assemble fittings; check insertion depth Remarks: _____	PM	12-19-24
11	Set offset angle and/or orientation Remarks: _____	PM	12-19-24
12	☒ Perform crimp or swage on product/crimp set die-using Parker Catalog 4660, page K58 ☒ 1/2) 80C-PO8H ☐ 1/4) 80C-PO4H ☐ 3/8) 80C-PO6 ☐ 3/8) 80C-PO6H ☐ 1/8) 80C-PO2 ☐ 3/4) 80C-P12H	PM	12-19-24
13	Add special accessories after crimping/swaging		
14	Perform and record burst test results, if applicable Remarks: _____		
15	Air test, if applicable Test pressure Psi _____ Seconds _____ ; Pass/Fail (Circle One) Remarks: _____		
16	☒ Hydrostatic proof test Test pressure Psi <u>10,000</u> Seconds <u>30</u> <u>(Pass)</u> Fail (Circle One) Remarks: _____	PM	12-19-24
17	☒ Flush method water, and then air	PM	12-19-24
18	☒ Perform and record conductivity test; Meter <u>Megger Mit200</u> Hose resistance <u>0.00</u> (-) Electrode resistance <u>0.03</u> (=) Final hose resistance <u>0.03</u>	PM	12-19-24
19	☒ Final audit: Check boxes for items inspected, as applicable: ☒ Correct hose; ☒ Correct fittings; ☒ Correct customer PN	PM	12-19-24
20	☒ Check swage or crimp diameters: ☒ 5CNG-4-58 .668/.688 ☒ 5CNG-6-58 .785/.805 ☒ 5CNG-6-55 .675/.695 ☒ 5CNG-8-58 .900/.920 ☒ 5CNG-12-58 1.20/1.22	PM	12-19-24
*****100% VISUAL INSPECT FOR THE FOLLOWING*****			
21	☒ Hose fittings crimped; ☒ Air passes through assembly; ☒ Presence of threads	PM	12-19-24
20	☒ Cap and package hose	PM	12-19-24
21	☒ Certificate of Conformance for Materials Shipped (on back)	PM	12-19-24

3

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

7

FITTING SIZE

- 4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

1

CG SERIES
HOSE SIZE

- 4 1/4"
6 3/8"
8 1/2"
12 3/4"

4

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD
06 JIC FEMALE SWIVEL
07 FEMALE PIPE SWIVEL

8

FITTING SIZE

- 4 1/4"
6 3/8"
8 1/2"
10 5/8"
12 3/4"

BREAK-AWAY OR
DISPENSER END


cut 105"

11

FILL HOSE LENGTH

96"

FILL END



5

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE

9

FITTING SIZE

- 2 1/8"
4 1/4"
6 3/8"

2

CG SERIES

- HOSE SIZE
4 1/4"
6 3/8"

6

FITTING TYPE

- 01 NPT MALE
02 NPT FEMALE
03 JIC MALE
04 SAE 45 MALE
05 SAE O-RING STRAIGHT THREAD

10

FITTING SIZE

- 2 1/8"
4 1/4"
6 3/8"

05 SAE O-RING STRAIGHT THREAD

06 JIC FEMALE SWIVEL

07 FEMALE PIPE SWIVEL

06 JIC FEMALE SWIVEL

07 FEMALE PIPE SWIVEL

WORK ORDER # JWP041224

5CNG12/5CNG6-0606/0506-1212/66-96"

FILL HOSE

TULSA GAS TECHNOLOGIES, INC.
10117 EAST 48TH STREET
TULSA, OK 74148

018-686-2841 FAX: 018-686-2857

DATE: 03/27/97

DESIGNED BY: C. SEWELL

DRAWN BY: C.R.S.

CHECKED BY: SCALP

NCFE

3

FITTING TYPE

01 NPT MALE

02 NPT FEMALE

03 JIC MALE

04 SAE 45 MALE

05 SAE O-RING STRAIGHT THREAD

06 JIC FEMALE SWIVEL

07 FEMALE PIPE SWIVEL

7

FITTING SIZE

4 1/4"

6 3/8"

8 1/2"

10 5/8"

12 3/4"

1

CG SERIES

HOSE SIZE

4 1/4"

6 3/8"

8 1/2"

12 3/4"

4

FITTING TYPE

01 NPT MALE

02 NPT FEMALE

03 JIC MALE

04 SAE 45 MALE

05 SAE O-RING STRAIGHT THREAD

06 JIC FEMALE SWIVEL

07 FEMALE PIPE SWIVEL

8

FITTING SIZE

4 1/4"

6 3/8"


8 1/2"

10 5/8"

12 3/4"

BREAK-AWAY OR
DISPENSER END11 FILL HOSE LENGTH
36"

FILL END

SHEREX CT1000 use 1/4" VENT ONLY 5/8"
SHEREX CT5000 use 3/8" VENT ONLY

5

FITTING TYPE

01 NPT MALE

02 NPT FEMALE

03 JIC MALE

04 SAE 45 MALE

05 SAE O-RING STRAIGHT THREAD

06 JIC FEMALE SWIVEL

07 FEMALE PIPE SWIVEL

2

CG SERIES

HOSE SIZE

4 1/4"

6 3/8"

6

FITTING TYPE

01 NPT MALE

02 NPT FEMALE

03 JIC MALE

04 SAE 45 MALE

05 SAE O-RING STRAIGHT THREAD

06 JIC FEMALE SWIVEL

07 FEMALE PIPE SWIVEL

10

FITTING SIZE

2 1/8"

4 1/4"

6 3/8"

WORK ORDER #DWPC041224

5CNG 12/5CNG 6-06 06/05 06-1212/66-36"

FILL HOSE

TULSA GAS TECHNOLOGIES, INC.
1011 EAST MAIN STREET
TULSA, OK 74106

DATE: 03/27/97

DESIGNED BY: C. SEWELL

CHECKED BY:

SCALE: NONE