ANNUAL VEHICLE INSPECTION REPORT

vin# 13 YBF1020KC125501 S/N 20011282
 VEHICLE HISTORY RECORD

 REPORT NUMBER
 FLEET UNIT NUMBER

 021720
 72481

 DATE 2-17-2020

2/00 000 1000	
MOTOR CARRIER OPERATOR	INSPECTOR'S NAME (PRINT OR TYPE)
CenterPoint Energy	Christopher Northup
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.
2205 E. Roosevelt Rd	☐ YES
CITY, STATE, ZIP CODE	VEHICLE IDENTIFICATION (▶ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☑ OTHER
FITTIE KOCK, MIN MALAUS	7401
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS	INSPECTION AGENCY/LOCATION (OPTIONAL)
☐ (OTHER)	Tulsa Gas Tech / Tulsa, OK
	, , , , , , , , , , , , , , , , , , , ,

□ (OTHER)		Tuisa Cas	Itch	1 14159, UK
to the Epitania against mountain resolution	VEHICLE	COMPONENTS INSPECTED	osao nidarentei de tima	(4) (4) (5) (1) (4) (5) (6) (6) (6) (6) (6) (6) (6) (6) (6) (6
OK REEDS REPAIRED DATE ITEM	OK REPAIR REPAIRED DATE	ITEM	OK REPAIR DATE	ITEM
1. BRAKE SYSTEM	and a historian	6. SAFE LOADING	(Settingoli)	10. TIRES
a. Service Brakes b. Parking Brake System c. Brake Drums or Rotors d. Brake Hose e. Brake Tubing f. Low Pressure Warning Device g. Tractor Protection Valve h. Air Compressor i. Electric Brakes j. Hydraulic Brakes k. Vacuum Systems l. Antilock Brake System m. Automatic Brake Adjuste	137	 a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway. b. Protection against shifting cargo. c. Container securement devices on intermodal equipment. 7. STEERING MECHANISM a. Steering Wheel Free Play b. Steering Column c. Front Axle Beam and All 	MA A	a. Tires on any steering axle of a power unit. b. All other tires. c. Installation of speed-restricted tires unless specifically designated by motor carrier. 11. WHEELS AND RIMS a. Lock or Side Ring b. Wheels and Rims c. Fasteners d. Welds 12. WINDSHIELD GLAZING Requirements and exceptions
2. COUPLING DEVICES a. Fifth Wheels b. Pintle Hooks c. Drawbar/Towbar Eye d. Drawbar/Towbar Tongue e. Safety Devices f. Saddle-Mounts 3. EXHAUST SYSTEM		Steering Components Other Than Steering Column d. Steering Gear Box e. Pitman Arm f. Power Steering g. Ball and Socket Joints h. Tie Rods and Drag Links	NA	as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions). 13. WINDSHIELD WIPERS Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
a. Exhaust system leaking forward of or directly bel the driver/sleeper compartment. b. Bus exhaust system	ww	i. Nutsj. Steering System8. SUSPENSIONa. Any U-bolt(s), spring	NA	14. MOTORCOACH SEATS Any passenger seat that is not securely fastened to the vehicle structure.
leaking or discharging in violation of standard. c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel sup or any combustible part the motor vehicle. 4. FUEL SYSTEM a. Visible leak. b. Fuel tank filler cap missic. Fuel tank securely attact 5. LIGHTING DEVICES All lighting devices and reflectors required by Part 3 shall be operable.	e ply, of	hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position. b. Spring Assembly c. Torque, Radius or Tracking Components 9. FRAME a. Frame Members b. Tire and Wheel Clearance c. Adjustable Axle Assemblies (Sliding Subframes)		List any other condition(s) which may prevent safe operation of this vehicle.
INSTRUCTIONS: MARK COLUMN ENTRIES TO VE	IFY INSPECTION:	· · · · · · · · · · · · · · · · · · ·	_ IF ITEMS DO I	NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.