

ANNUAL VEHICLE INSPECTION REPORT

TGT Ser# 20081299

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
69892759	01957
DATE 7-15-2025	

MOTOR CARRIER OPERATOR Kansas Gas Services Topeka	INSPECTOR'S NAME (PRINT OR TYPE) Chris Sheets
ADDRESS 340 E 1st St	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Topeka, KS 66603	VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 13YBF1020LC125970
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) Tulsa Gas Technologies

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒			1. BRAKE SYSTEM	☒			6. SAFE LOADING				12. WINDSHIELD GLAZING
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			b. Parking Brake System	☒			b. Front End Structure		☒		13. WINDSHIELD WIPERS
☒			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices				No missing, damaged, or inoperable wipers.
		NA	d. Brake Hose			NA			☒		14. MOTORCOACH SEATS
		NA	e. Brake Tubing			NA					Seats securely fastened to the vehicle structure.
		NA	f. Low Pressure Warning Device			NA	7. STEERING MECHANISM				15. REAR IMPACT GUARD
		NA	g. Tractor Protection Valve			NA	a. Steering Wheel Free Play				In place, securely attached, proper size, proper placement (see 393.86).
		NA	h. Air Compressor			NA	b. Steering Column				16. OTHER
☒			i. Electric Brakes			NA	c. Front Axle Beam/All Other Steering Components				List any other condition(s) which may prevent safe operation of this vehicle.
		NA	j. Hydraulic Brakes			NA	d. Steering Gear Box				
		NA	k. Vacuum Systems			NA	e. Pitman Arm				
☒			l. Antilock Brake System			NA	f. Power Steering				
☒			m. Automatic Brake Adjusters			NA	g. Ball and Socket Joints				
		NA	2. COUPLING DEVICES			NA	h. Tie Rods and Drag Links				
☒		NA	a. Fifth Wheels			NA	i. Nuts				
		NA	b. Pintle Hooks			NA	j. Steering System				
		NA	c. Drawbar/Towbar Eye			NA	8. SUSPENSION				
☒		NA	d. Drawbar/Towbar Tongue			NA	a. Axle Positioning Parts				
		NA	e. Safety Devices	☒			b. Spring Assembly				
		NA	f. Saddle-Mounts	☒			c. Torque, Radius or Tracking Components				
		NA	3. EXHAUST SYSTEM	☒			9. FRAME				
		NA	a. No leaks forward of/ directly below the driver/sleeper compartment.	☒			a. Frame Members				
		NA	b. Bus: No leaking/ discharging in violation of standard.	☒			b. Tire and Wheel Clearance				
		NA	c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.			NA	c. Adjustable Axle Assemblies (Sliding Subframes)				
		NA	4. FUEL SYSTEM			NA	10. TIRES				
		NA	a. No visible leak.	☒			a. Steer-Axle Tires				
		NA	b. Fuel Tank Filler Cap			NA	b. All Other Tires				
		NA	c. Fuel tank securely attached.			NA	c. Speed-Restricted Tires				
☒			5. LIGHTING DEVICES	☒			11. WHEELS AND RIMS				
			All required lights/reflectors operable.	☒			a. Lock or Side Ring				
				☒			b. Wheels and Rims				
				☒			c. Fasteners				
				☒			d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, ☒ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.