

KANSAS GAS SERVICE

RECORD OF ANNUAL INSPECTION - 49 CFR, 396.17-23

FORM 12030

PREPARE A SEPARATE REPORT FOR EACH VEHICLE INSPECTED.

VEHICLE TYPE	<input type="checkbox"/> TRUCK <input checked="" type="checkbox"/> TRAILER	MODEL Utility	MAKE Star	YEAR 2020
EQUIPMENT UNIT NO. 01956	VEHICLE IDENTIFICATION NO. 13YBF1024CC125972			
DOMICILE LOCATION Overland Park KS	TAG NO./ STATE 508597 65			
INSPECTION LOCATION STREET ADDRESS 1421 N 3rd ST				
CITY KANSAS CITY	STATE KS	ZIP 66101		
INSPECTOR'S NAME Stewart		ID NO. 21823		

REPORT OF CONDITION

OK		REPAIR	OK		REPAIR	OK		REPAIR
BRAKE			LIGHTING			FUEL SYSTEM		
Adjustment	/		Headlights			Tank(s)		
Mechanical Components	/		Tail/Stop	/		Lines		
Drum/Rotor	/		Clearance/Marker	/				
Hose/Tubing	/		Identification	/				
Lining	/		Reflectors	/				
Low Air Warning			Other					
Trailer Air Supply			CAB/BODY			SUSPENSION		
Compressor			Access			Springs		
Parking Brakes			Eqpt./Load Secure	/		Attachments		/
Other			Tie-Downs			Sliders		
COUPLERS			Headerboard					
Fifth-Wheel & Mount			Other			FRAME		
Pin/Upper Plate			STEARING			Parking Brakes		
Pintle-Hook/Eye	/		Adjustment			Other		
Safety Chain(s)	/		Column/Gear					
EXHAUST			Axle			TIRES		
Leaks	/		Linkage			Tread		/
Placement			Power Steering			Inflation		/
REMARKS	<hr/> <hr/> <hr/> <hr/> <hr/>		Other			Damage		
	<hr/> <hr/> <hr/> <hr/> <hr/>					Other		
	<hr/> <hr/> <hr/> <hr/> <hr/>					WHEELS/RIMS		
	<hr/> <hr/> <hr/> <hr/> <hr/>					Fasteners		
	<hr/> <hr/> <hr/> <hr/> <hr/>					Disc/Spoke		/
	<hr/> <hr/> <hr/> <hr/> <hr/>					WINDSHIELD		
	<hr/> <hr/> <hr/> <hr/> <hr/>							
	<hr/> <hr/> <hr/> <hr/> <hr/>					WINDSHIELD WIPERS		
	<hr/> <hr/> <hr/> <hr/> <hr/>							
	<hr/> <hr/> <hr/> <hr/> <hr/>					MIRRORS		
	<hr/> <hr/> <hr/> <hr/> <hr/>							

THIS VEHICLE HAS BEEN INSPECTED AND REPAIRED AS NEEDED TO COMPLY WITH 49 CFR PART 396, APPENDIX G.

CERTIFIED INSPECTOR'S SIGNATURE  DATE 8-4-25