

ANNUAL VEHICLE INSPECTION REPORT

TGT MC ID# 2812566
TGT S/N - 25031497

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
69892749	18513
DATE 5-14-25	

MOTOR CARRIER OPERATOR New Mexico Gas Co	INSPECTOR'S NAME (PRINT OR TYPE) Greg Miller
ADDRESS 4625 Edith Blvd Rd NE	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Albuquerque NM 87107	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 585140810JP010061
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) Tulsa Gas Technologies, Tulsa, OK

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
			a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			b. Parking Brake System				b. Front End Structure				13. WINDSHIELD WIPERS
			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices				No missing, damaged, or inoperable wipers.
			d. Brake Hose								14. MOTORCOACH SEATS
			e. Brake Tubing				7. STEERING MECHANISM				Seats securely fastened to the vehicle structure.
			f. Low Pressure Warning Device				a. Steering Wheel Free Play				15. REAR IMPACT GUARD
			g. Tractor Protection Valve				b. Steering Column				In place, securely attached, proper size, proper placement (see 393.86).
			h. Air Compressor				c. Front Axle Beam/All Other Steering Components				16. OTHER
			i. Electric Brakes				d. Steering Gear Box				List any other condition(s) which may prevent safe operation of this vehicle.
			j. Hydraulic Brakes				e. Pitman Arm				
			k. Vacuum Systems				f. Power Steering				
			l. Antilock Brake System				g. Ball and Socket Joints				
			m. Automatic Brake Adjusters				h. Tie Rods and Drag Links				
			2. COUPLING DEVICES				i. Nuts				
			a. Fifth Wheels				j. Steering System				
			b. Pintle Hooks				8. SUSPENSION				
			c. Drawbar/Towbar Eye				a. Axle Positioning Parts				
			d. Drawbar/Towbar Tongue				b. Spring Assembly				
			e. Safety Devices				c. Torque, Radius or Tracking Components				
			f. Saddle-Mounts				9. FRAME				
			3. EXHAUST SYSTEM				a. Frame Members				
			a. No leaks forward of/directly below the driver/sleeper compartment.				b. Tire and Wheel Clearance				
			b. Bus: No leaking/discharging in violation of standard.				c. Adjustable Axle Assemblies (Sliding Subframes)				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				10. TIRES				
			4. FUEL SYSTEM				a. Steer-Axle Tires				
			a. No visible leak.				b. All Other Tires				
			b. Fuel Tank Filler Cap				c. Speed-Restricted Tires				
			c. Fuel tank securely attached.				11. WHEELS AND RIMS				
			5. LIGHTING DEVICES				a. Lock or Side Ring				
			All required lights/reflectors operable.				b. Wheels and Rims				
							c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.