

# ANNUAL VEHICLE INSPECTION REPORT

TGT US DOT #2812 566  
 TGT S/N-25061513  
 5 DOT 3K

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
69892782	18512
DATE <span style="font-size: 1.2em;">10/30/2025</span>	

MOTOR CARRIER OPERATOR <span style="font-size: 1.2em;">New Mexico Gas Co</span>	INSPECTOR'S NAME (PRINT OR TYPE) <span style="font-size: 1.2em;">NICK BAKOS</span>
ADDRESS <span style="font-size: 1.2em;">601 W Elm St</span>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <span style="font-size: 1.2em;">Farmington NM 87401</span>	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER <span style="font-size: 1.2em;">5851408191P010060</span>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) <span style="font-size: 1.2em;">Tulsa Gas Technologies Tulsa OK</span>

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	
<b>1. BRAKE SYSTEM</b>												
			a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.				<b>12. WINDSHIELD GLAZING</b>	
			b. Parking Brake System				b. Front End Structure				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).	
			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices				<b>13. WINDSHIELD WIPERS</b>	
			d. Brake Hose				<b>7. STEERING MECHANISM</b>					No missing, damaged, or inoperable wipers.
			e. Brake Tubing				a. Steering Wheel Free Play				<b>14. MOTORCOACH SEATS</b>	
			f. Low Pressure Warning Device				b. Steering Column				Seats securely fastened to the vehicle structure.	
			g. Tractor Protection Valve				c. Front Axle Beam/All Other Steering Components				<b>15. REAR IMPACT GUARD</b>	
			h. Air Compressor				d. Steering Gear Box				In place, securely attached, proper size, proper placement (see 393.86).	
			i. Electric Brakes				e. Pitman Arm				<b>16. OTHER</b>	
			j. Hydraulic Brakes				f. Power Steering				List any other condition(s) which may prevent safe operation of this vehicle.	
			k. Vacuum Systems				g. Ball and Socket Joints					
			l. Antilock Brake System				h. Tie Rods and Drag Links					
			m. Automatic Brake Adjusters				i. Nuts					
							j. Steering System					
<b>2. COUPLING DEVICES</b>												
			a. Fifth Wheels				<b>8. SUSPENSION</b>					
			b. Pintle Hooks				a. Axle Positioning Parts					
			c. Drawbar/Towbar Eye				b. Spring Assembly					
			d. Drawbar/Towbar Tongue				c. Torque, Radius or Tracking Components					
			e. Safety Devices				<b>9. FRAME</b>					
			f. Saddle-Mounts				a. Frame Members					
<b>3. EXHAUST SYSTEM</b>												
			a. No leaks forward of/ directly below the driver/ sleeper compartment.				b. Tire and Wheel Clearance					
			b. Bus: No leaking/ discharging in violation of standard.				c. Adjustable Axle Assemblies (Sliding Subframes)					
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				<b>10. TIRES</b>					
<b>4. FUEL SYSTEM</b>												
			a. No visible leak.				a. Steer-Axle Tires					
			b. Fuel Tank Filler Cap				b. All Other Tires					
			c. Fuel tank securely attached.				c. Speed-Restricted Tires					
<b>5. LIGHTING DEVICES</b>												
			All required lights/reflectors operable.				<b>11. WHEELS AND RIMS</b>					
							a. Lock or Side Ring					
							b. Wheels and Rims					
							c. Fasteners					
							d. Welds					

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

**CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.**