GT S/N - 25081522

O DOT 12K

DOT # - 2812566

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
69892797	298023
DATE 05/27/26	

OTOR CARRIER OPERATOR: Phoenix Energy Corp	INSPECTOR'S NAME (PRINT OR TYPE): Chris Sheets
DRESS: 164 LAURIS LAKE LANE	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
Y, STATE, ZIP CODE: PELL CITY, AL 35125	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER: 4T9TIVE29TT298023
HICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL): Tulsa Gas Technologies

VEHICLE COMPONENTS INSPECTED

NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
		1. BRAKE SYSTEM				**6. SAFE LOADING**				**12. WINDSHIELD GLAZING**
		a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
NA		b. Parking Brake System	✓					NA		
		c. Brake Drums or Rotors	✓			b. Front End Structure				**13. WINDSHIELD WIPERS**
NA		d. Brake Hose				c. Intermodal Container Securement Devices		NA		No missing, damaged, or inoperable wipers.
NA		e. Brake Tubing		NA						**14. MOTORCOACH SEATS**
NA		f. Low Pressure Warning Device				**7. STEERING MECHANISM**				Seats securely fastened to the vehicle structure.
NA		g. Tractor Protection Valve		NA		a. Steering Wheel Free Play		NA		
NA		h. Air Compressor		NA		b. Steering Column				**15. REAR IMPACT GUARD**
		i. Electric Brakes				c. Front Axle Beam/All Other Steering Components		NA		In place, securely attached, proper size, proper placement (see 393.86).
NA		j. Hydraulic Brakes		NA		d. Steering Gear Box				**16. OTHER**
NA		k. Vacuum Systems		NA		e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
NA		l. Antilock Brake System		NA		f. Power Steering		NA		
NA		m. Automatic Brake Adjusters		NA		g. Ball and Socket Joints				
		2. COUPLING DEVICES				h. Tie Rods and Drag Links				
NA		a. Fifth Wheels		NA		i. Nuts				
NA		b. Pintle Hooks		NA		j. Steering System				
		c. Drawbar/Towbar Eye				**8. SUSPENSION**				
NA		d. Drawbar/Towbar Tongue	✓			a. Axle Positioning Parts				
		e. Safety Devices	✓			b. Spring Assembly				
NA		f. Saddle-Mounts	✓			c. Torque, Radius or Tracking Components				
		3. EXHAUST SYSTEM				**9. FRAME**				
		a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓			a. Frame Members				
NA		b. Bus: No leaking/ discharging in violation of standard.	✓			b. Tire and Wheel Clearance				
		c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
NA						**10. TIRES**				
		4. FUEL SYSTEM		NA		a. Steer-Axle Tires				
NA		a. No visible leak.	✓			b. All Other Tires				
NA		b. Fuel Tank Filler Cap		NA		c. Speed-Restricted Tires				
NA		c. Fuel tank securely attached.				**11. WHEELS AND RIMS**				
		5. LIGHTING DEVICES		NA		a. Lock or Side Ring				
		All required lights/reflectors operable.	✓			b. Wheels and Rims				
			✓			c. Fasteners				
			✓			d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

RTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN CORDANCE WITH 49 CFR PART 396.

/right 2022 J. J. Keller & Associates, Inc.
nah, WI • JJKeller.com • (800) 327-6868
ed in the USA

DUPLICATE

3128
(Rev. 1/22)