

**ANNUAL VEHICLE INSPECTION REPORT**

TGT S/N 18061218

DOT # 2812566

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
69892794	18501
DATE 3-3-2026	

MOTOR CARRIER OPERATOR <b>New Mexico Gas</b>	INSPECTOR'S NAME (PRINT OR TYPE) <b>Chris Sheets</b>
ADDRESS <b>6 Forest Lane</b>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <b>Santa Fe, NM 87508</b>	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER <b>13YBF14243C123890</b>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) <b>Tulsa Gas Technologies</b>

**VEHICLE COMPONENTS INSPECTED**

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	
<b>1. BRAKE SYSTEM</b>			a. Service Brakes	<b>6. SAFE LOADING</b>			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	<b>12. WINDSHIELD GLAZING</b>			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).	
✓			b. Parking Brake System				b. Front End Structure	NA			<b>13. WINDSHIELD WIPERS</b>	No missing, damaged, or inoperable wipers.
✓			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	NA			<b>14. MOTORCOACH SEATS</b>	Seats securely fastened to the vehicle structure.
✓			d. Brake Hose				<b>7. STEERING MECHANISM</b>			<b>15. REAR IMPACT GUARD</b>	In place, securely attached, proper size, proper placement (see 393.86).	
✓			e. Brake Tubing				a. Steering Wheel Free Play	NA			<b>16. OTHER</b>	List any other condition(s) which may prevent safe operation of this vehicle.
	NA		f. Low Pressure Warning Device				b. Steering Column					
	NA		g. Tractor Protection Valve				c. Front Axle Beam/All Other Steering Components					
	NA		h. Air Compressor				d. Steering Gear Box					
✓			i. Electric Brakes				e. Pitman Arm					
	NA		j. Hydraulic Brakes				f. Power Steering					
	NA		k. Vacuum Systems				g. Ball and Socket Joints					
	NA		l. Antilock Brake System				h. Tie Rods and Drag Links					
	NA		m. Automatic Brake Adjusters				i. Nuts					
<b>2. COUPLING DEVICES</b>							j. Steering System					
✓			a. Fifth Wheels				<b>8. SUSPENSION</b>					
	NA		b. Pintle Hooks				a. Axle Positioning Parts					
	NA		c. Drawbar/Towbar Eye				b. Spring Assembly					
	NA		d. Drawbar/Towbar Tongue				c. Torque, Radius or Tracking Components					
	NA		e. Safety Devices				<b>9. FRAME</b>					
	NA		f. Saddle-Mounts				a. Frame Members					
	NA						b. Tire and Wheel Clearance					
	NA						c. Adjustable Axle Assemblies (Sliding Subframes)					
<b>3. EXHAUST SYSTEM</b>							<b>10. TIRES</b>					
	NA		a. No leaks forward of/ directly below the driver/ sleeper compartment.				a. Steer-Axle Tires					
	NA		b. Bus: No leaking/ discharging in violation of standard.				b. All Other Tires					
	NA		c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				c. Speed-Restricted Tires					
<b>4. FUEL SYSTEM</b>							<b>11. WHEELS AND RIMS</b>					
	NA		a. No visible leak.				a. Lock or Side Ring					
	NA		b. Fuel Tank Filler Cap				b. Wheels and Rims					
	NA		c. Fuel tank securely attached.				c. Fasteners					
<b>5. LIGHTING DEVICES</b>							d. Welds					
✓			All required lights/reflectors operable.									

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.