

S/N-21071318

TH

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
122721-03	8992
DATE 12-27-21	

MOTOR CARRIER OPERATOR  
**CenterPoint Energy Resources Corp**  
 ADDRESS  
**2444 Levy St**  
 CITY, STATE, ZIP CODE  
**Shreveport, LA 71103**  
 VEHICLE TYPE  TRACTOR  TRAILER  TRUCK  BUS  
 (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)  
**Jonathan Caperton**  
 THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.  
 YES  
 VEHICLE IDENTIFICATION (✓ AND COMPLETE)  LIC. PLATE NO.  VIN  OTHER  
**4T9T1UC27MT298008**  
 INSPECTION AGENCY/LOCATION (OPTIONAL)  
**Msu Gas Technologies**

**VEHICLE COMPONENTS INSPECTED**

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
<b>1. BRAKE SYSTEM</b>			a. Service Brakes	<b>6. SAFE LOADING</b>			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	<b>10. TIRES</b>			a. Tires on any steering axle of a power unit.
✓	NA		b. Parking Brake System	✓			b. Protection against shifting cargo.	✓	NA		b. All other tires.
✓	NA		c. Brake Drums or Rotors				c. Container securement devices on intermodal equipment.		NA		c. Installation of speed-restricted tires unless specifically designated by motor carrier.
	NA		d. Brake Hose								
	NA		e. Brake Tubing	✓							
	NA		f. Low Pressure Warning Device								
	NA		g. Tractor Protection Valve								
	NA		h. Air Compressor		NA						
✓	NA		i. Electric Brakes					✓	NA		<b>11. WHEELS AND RIMS</b>
	NA		j. Hydraulic Brakes					✓			a. Lock or Side Ring
	NA		k. Vacuum Systems		NA			✓			b. Wheels and Rims
✓	NA		l. Antilock Brake System					✓			c. Fasteners
	NA		m. Automatic Brake Adjusters								d. Welds
<b>2. COUPLING DEVICES</b>				<b>7. STEERING MECHANISM</b>			a. Steering Wheel Free Play	<b>12. WINDSHIELD GLAZING</b>			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
	NA		a. Fifth Wheels				b. Steering Column				
	NA		b. Pintle Hooks				c. Front Axle Beam and All Steering Components Other Than Steering Column		NA		
✓			c. Drawbar/Towbar Eye				d. Steering Gear Box				
✓			d. Drawbar/Towbar Tongue				e. Pitman Arm				
✓			e. Safety Devices				f. Power Steering				
	NA		f. Saddle-Mounts				g. Ball and Socket Joints		NA		<b>13. WINDSHIELD WIPERS</b>
<b>3. EXHAUST SYSTEM</b>							h. Tie Rods and Drag Links				Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
	NA		a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.				i. Nuts				
			b. Bus exhaust system leaking or discharging in violation of standard.				j. Steering System				
			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓			<b>8. SUSPENSION</b>				<b>14. MOTORCOACH SEATS</b>
							a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				Any passenger seat that is not securely fastened to the vehicle structure.
							b. Spring Assembly				
							c. Torque, Radius or Tracking Components				
<b>4. FUEL SYSTEM</b>							<b>9. FRAME</b>				<b>15. OTHER</b>
	NA		a. Visible leak.				a. Frame Members				List any other condition(s) which may prevent safe operation of this vehicle.
			b. Fuel tank filler cap missing.				b. Tire and Wheel Clearance				
			c. Fuel tank securely attached.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
<b>5. LIGHTING DEVICES</b>											
✓			All lighting devices and reflectors required by Part 393 shall be operable.								

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.