TGI - S/N - 22121349

ANNUAL VEHICLE INSPECTION REPORT

4T9T1UE29PT298013

319-526-5206

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
091323-1	
DATE 9-13-2023	

MOTOR CARRIER OPERATOR: Liberty (Midstates Natural Gas) Corp.	INSPECTOR'S NAME (PRINT OR TYPE): Chris Northup
ADDRESS: PO Box 127	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES
CITY, STATE, ZIP CODE: Joplin, MO 64802	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER: 4T9T1UE29PT298013
VEHICLE TYPE ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL): Tulsa Gas Tech / Tulsa OK

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
✓			a. Service Brakes
N/A			b. Parking Brake System
✓			c. Brake Drums or Rotors
N/A			d. Brake Hose
N/A			e. Brake Tubing
N/A			f. Low Pressure Warning Device
N/A			g. Tractor Protection Valve
N/A			h. Air Compressor
✓			i. Electric Brakes
N/A			j. Hydraulic Brakes
N/A			k. Vacuum Systems
N/A			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
N/A			a. Fifth Wheels
✓			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
✓			d. Drawbar/Towbar Tongue
✓			e. Safety Devices
N/A			f. Saddle-Mounts
3. EXHAUST SYSTEM			
N/A			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.
N/A			b. Bus exhaust system leaking or discharging in violation of standard.
N/A			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.
4. FUEL SYSTEM			
N/A			a. Visible leak.
N/A			b. Fuel tank filler cap missing.
N/A			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
✓			All lighting devices and reflectors required by Part 393 shall be operable.
6. SAFE LOADING			
	✓		a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
	✓		b. Protection against shifting cargo.
	N/A		c. Container securement devices on intermodal equipment.
7. STEERING MECHANISM			
N/A			a. Steering Wheel Free Play
N/A			b. Steering Column
N/A			c. Front Axle Beam and All Steering Components Other Than Steering Column
N/A			d. Steering Gear Box
N/A			e. Pitman Arm
N/A			f. Power Steering
N/A			g. Ball and Socket Joints
N/A			h. Tie Rods and Drag Links
N/A			i. Nuts
N/A			j. Steering System
8. SUSPENSION			
	✓		a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
	✓		b. Spring Assembly
	✓		c. Torque, Radius or Tracking Components
9. FRAME			
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
N/A			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
N/A			a. Tires on any steering axle of a power unit.
✓			b. All other tires. 70 psi
N/A			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
11. WHEELS AND RIMS			
N/A			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners TQ ✓
✓			d. Welds
12. WINDSHIELD GLAZING			
N/A			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
13. WINDSHIELD WIPERS			
N/A			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
14. MOTORCOACH SEATS			
N/A			Any passenger seat that is not securely fastened to the vehicle structure.
15. OTHER			
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2016 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

ORIGINAL