



7441-A

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47169E

Work Order: W14004658

Customer PO#: 072215-7441

Customer: PRIORITY PROJECTS LTD Date: 07/11/2022
 Facility: LSD: PSV Location:
 A#: Vessel SN: Cust Id:
 Cust. Ref.: Valve PO: 072215-7441 PO LINE#:
 Cust. WO#: Cust AFE#: Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-43G51T32U1 Serial: RVC00019170 Seat: SOFT
 Conn. Threaded Inlet: 2" MNPT Orifice: 0.472 Outlet: 2" FNPT Vacuum: N/A
 Set Press. 1,000 PSI Back Press.: N/A PSI CDT: N/A PSI Temp: 70 F Cap: 7,889 SCFM
 Lift Lever Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CLADI

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? Reset Required?

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 07/2022
 Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: Outlet:
 Inlet: Clean Inlet Plugged: Outlet: Clean Outlet Plugged: Initial Insp. Signoff: Francis Escara

PRETEST 1

Simmer: 0 Set Press: Reseat: Leakage: Test Gauge:
 Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
 Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

ITEM	CLEAN	OILY	RUSTY	CARBON	PITTED	CORRODED	SCALE	VIBRATION	GROOVED	DENTED	GALLING	GOUGED	OTHER	Machined	Lapped	Polished	Replaced	Replace Next Service	COMMENTS
DISC														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
NOZZLE														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
CAP-LEVER ASSY														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
COMP SCREW and LOC														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
AS FOUND: _____ AS LEFT: _____																			
SPRING and BUTTONS														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
SPINDLE / STEM														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
STEM RETAINER														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
DISC HOLDER														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
GUIDE / UPPER RING														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
LOWER RING														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
RING PIN(S)														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BELLOWS														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
GASKET / SEALS														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
CONNECTION ENDS														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
OTHER														<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

DISC: : ACT - NOZZLE: ACT - SPRING NUMBER:
 Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: PPSI
 Reseat: PSI Leakage Acceptable: B.P. Test: PSI Vacuum: N/A
 ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG-03/04 Set Press Def: (Select Set Press Def)
 Tested by: Ricardo Santos Date Final Tested: 07/22/2022

FINAL INSPECTION:

SEAL: Top: Bottom: End Protectors Installed: Painted: Palletized: Ship Container: Flex Gaskets Supplied:
 Final Inspection: Wally Praxedes Customer Inspection:
 Comments: TESTING: Leak tested at 90% of Set Pressure as per API 527.



7441-A

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47166E

Work Order: W14004658

Customer PO#: 072215-7441

Customer: PRIORITY PROJECTS LTD

Date: 07/11/2022

Facility: LSD:

PSV Location:

A#: Vessel SN:

Cust Id:

Cust. Ref.: Valve PO: 072215-7441

PO LINE#:

Cust. WO#: Cust AFE#:

Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-43F61P34C1 Serial: RVC00019167 Seat: SOFT
Conn. Threaded Inlet: 2" MNPT Orifice: 0.337 Outlet: 2" FNPT Vacuum: N/A
Set Press. 2,100 PSI Back Press.: N/A PSI CDTP: N/A PSI Temp: 70 F Cap: 11,747 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CLADL

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? [] Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 07/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Francis Escara

PRETEST 1

Simmer: 0 Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns: ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUGED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS

DISC: : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: PPSPI
Reseat: PSI Leakage Acceptable: [x] B.P. Test: PSI Vacuum:
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG-03/04 Set Press Def: POP
Tested by: Ricardo Santos Date Final Tested: 07/22/2022

FINAL INSPECTION:

SEAL: Top: [x] Bottom: [] End Protectors Installed: [x] Painted: [] Palletized: [] Ship Container: [x] Flex Gaskets Supplied: []
Final Inspection: Wally Praxedes Customer Inspection:
Comments: TESTING: Leak tested at 90% of Set Pressure as per API 527.



7441-A

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47164E

Work Order: W14004658

Customer PO#: 072215-7441

Customer: PRIORITY PROJECTS LTD

Date: 07/11/2022

Facility: LSD:

PSV Location:

A#: Vessel SN:

Cust Id:

Cust. Ref.: Valve PO: 072215-7441

PO LINE#:

Cust. WO#: Cust AFE#:

Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-43F61P34C1 Serial: RVC00019166 Seat: SOFT
Conn. Threaded Inlet: 2" MNPT Orifice: 0.337 Outlet: 2" FNPT Vacuum: N/A
Set Press. 2,100 PSI Back Press.: N/A PSI CDTP: N/A PSI Temp: 70 F Cap: 11,747 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CLADE

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? [] Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 07/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Francis Escara

PRETEST 1

Simmer: 0 Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns: ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUGED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS

DISC : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: PPSI
Reseat: PSI Leakage Acceptable: [x] B.P. Test: PSI Vacuum: N/A
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG-03/04 Set Press Def: POP
Tested by: Ricardo Santos Date Final Tested: 07/22/2022

FINAL INSPECTION:

SEAL: Top: [x] Bottom: [] End Protectors Installed: [x] Painted: [] Palletized: [] Ship Container: [x] Flex Gaskets Supplied: []
Final Inspection: Wally Praxedes Customer Inspection:
Comments: TESTING: Leak tested at 90% of Set Pressure as per API 527.



7441-A

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton
Work Order: W14004933-2

UVL ID#: 48151E
Customer PO#: 092211-7446

Customer: PRIORITY PROJECTS LTD
Facility: NISKU
A#:
Cust. Ref.:
Cust. WO#:

LSD:
Vessel SN:
Valve PO: 092211-7446
Cust AFE#:

Date: 12/07/2022
PSV Location:
Cust Id:
PO LINE#:
Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-17D51V0711 Serial: RVC00022068 Seat: SOFT
Conn. Threaded Inlet: 1" MNPT Orifice: D Outlet: 1" FNPT Vacuum:
Set Press. 125 PSI Back Press.: N/A PSI CDTP: N/A PSI Temp: 70 F Cap: 278 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CL/

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 12/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Wally Praxedes

PRETEST 1

[X] Pretest Not Completed Pretest Not Completed Reason: New Valve
Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns for ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUGED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS.

DISC : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: 125 PSI
Reseat: PSI Leakage Acceptable: [X] B.P. Test: 60 PSI Vacuum: N/A
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG03/04 Set Press Def: POP
Tested by: Davin Steidel Date Final Tested: 12/08/2022

FINAL INSPECTION:

SEAL: Top: [X] Bottom: [] End Protectors Installed: [X] Painted: [] Palletized: [] Ship Container: [X] Flex Gaskets Supplied: []
Final Inspection: Wally Praxedes Customer Inspection:
Comments: TESTING: LEAK TESTED @90 PERCENT OF SET AS PER API527



7441-A

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47778E

Work Order: w14004933-1

Customer PO#: 092211-7446

Customer: PRIORITY PROJECTS LTD
Facility: NISKU
A#:
Cust. Ref.:
Cust. WO#:

LSD:
Vessel SN:
Valve PO: 092211-7446
Cust AFE#:

Date: 10/19/2022
PSV Location:
Cust Id:
PO LINE#:
Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-64K11T86U1 Serial: RVC00021050 Seat: SOFT
Conn. Flanged Inlet: 3" 300 RF Orifice: K Outlet: 4" 150 RF Vacuum:
Set Press. 300 PSI Back Press.: N/A PSI CDTP: N/A PSI Temp: 70 F Cap: 10,720 SCFM
Lift Lever Cap Assembly: Closed RFID: Code Symbol: UV CRN#: OG8841.5CL

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? [checked] Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 10/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Wally Praxedes

PRETEST 1

Simmer: 0 Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns for component types (CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUNDED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace) and rows for various valve components like DISC, NOZZLE, CAP-LEVER ASSY, etc.

DISC: : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Simmer: Set Pressure:
Reseat: Leakage Acceptable: [] B.P. Test: Vacuum:
ADJ. RING SETTING (NOTCHES): Upper: Lower: Test Gauge: Set Press Def: POP
Tested by: Date Final Tested:

FINAL INSPECTION:

SEAL: Top: [] Bottom: [] End Protectors Installed: [] Painted: [] Palletized: [] Ship Container: [] Flex Gaskets Supplied: []
Final Inspection: Customer Inspection:
Comments:



7441-B

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47168E

Work Order: W14004658

Customer PO#: 072215-7441

Customer: PRIORITY PROJECTS LTD

Date: 07/11/2022

Facility: LSD:

PSV Location:

A#: Vessel SN:

Cust Id:

Cust. Ref.: Valve PO: 072215-7441

PO LINE#:

Cust. WO#: Cust AFE#:

Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-43G51T32U1 Serial: RVC00019171 Seat: SOFT
Conn. Threaded Inlet: 2" MNPT Orifice: 0.472 Outlet: 2" FNPT Vacuum: N/A
Set Press. 1,000 PSI Back Press.: N/A PSI CDTP: N/A PSI Temp: 70 F Cap: 7,889 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CLADL

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? [] Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 07/2022
Seal Condition: Top: Intact Bottom: N/A/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Francis Escara

PRETEST 1

Simmer: 0 Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns for ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUGED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS.

DISC: ; ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: PPSPI
Reseat: PSI Leakage Acceptable: [x] B.P. Test: PSI Vacuum: N/A
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG-03/04 Set Press Def: (Select Set Press Def)
Tested by: Ricardo Santos Date Final Tested: 07/22/2022

FINAL INSPECTION:

SEAL: Top: [x] Bottom: [] End Protectors Installed: [x] Painted: [] Palletized: [] Ship Container: [x] Flex Gaskets Supplied: []
Final Inspection: Wally Praxedes Customer Inspection:
Comments: TESTING: Leak tested at 90% of Set Pressure as per API 527.



7441-B

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47165E

Work Order: W14004658

Customer PO#: 072215-7441

Customer: PRIORITY PROJECTS LTD

Date: 07/11/2022

Facility: LSD:

PSV Location:

A#: Vessel SN:

Cust Id:

Cust. Ref.: Valve PO: 072215-7441

PO LINE#:

Cust. WO#: Cust AFE#:

Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-43F61P34C1 Serial: RVC00019169 Seat: SOFT
Conn. Threaded Inlet: 2" RF Orifice: 0.337 Outlet: 2" FNPT Vacuum: N/A
Set Press. 2,100 PSI Back Press.: N/A PSI CDTF: N/A PSI Temp: 70 F Cap: 11,747 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CLAD

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? [] Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 07/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Francis Escara

PRETEST 1

Simmer: 0 PSI Set Press: PSI Reseat: PSI Leakage: BPM Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns for ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUGED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS.

DISC : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: PPSI
Reseat: PSI Leakage Acceptable: [x] B.P. Test: PSI Vacuum: N/A
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG-03/04 Set Press Def: POP
Tested by: Ricardo Santos Date Final Tested: 07/22/2022

FINAL INSPECTION:

SEAL: Top: [x] Bottom: [] End Protectors Installed: [x] Painted: [] Palletized: [] Ship Container: [x] Flex Gaskets Supplied: []
Final Inspection: Wally Praxedes Customer Inspection:
Comments: TESTING: Leak tested at 90% of Set Pressure as per API 527.



7441-B

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47167E

Work Order: W14004658

Customer PO#: 072215-7441

Customer: PRIORITY PROJECTS LTD

Date: 07/11/2022

Facility: LSD:

PSV Location:

A#: Vessel SN:

Cust Id:

Cust. Ref.: Valve PO: 072215-7441

PO LINE#:

Cust. WO#: Cust AFE#:

Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-43F61P34C1 Serial: RVC00019168 Seat: SOFT
Conn. Threaded Inlet: 2" RF Orifice: 0.337 Outlet: 2" FNPT Vacuum: N/A
Set Press. 2,100 PSI Back Press.: N/A PSI CDT: N/A PSI Temp: 70 F Cap: 11,747 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CLAD

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? [] Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 07/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Francis Escara

PRETEST 1

Simmer: 0 PSI Set Press: PSI Reseat: PSI Leakage: BPM Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns: ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUGED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS

DISC: : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: PPSI
Reseat: PSI Leakage Acceptable: [x] B.P. Test: PSI Vacuum: N/A
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG-03/04 Set Press Def: POP
Tested by: Ricardo Santos Date Final Tested: 07/22/2022

FINAL INSPECTION:

SEAL: Top: [x] Bottom: [] End Protectors Installed: [x] Painted: [] Palletized: [] Ship Container: [x] Flex Gaskets Supplied: []
Final Inspection: Wally Praxedes Customer Inspection:
Comments: TESTING: Leak tested at 90% of Set Pressure as per API 527.



7441-B

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 48150E

Work Order: W14004933-2

Customer PO#: 092211-7446

Customer: PRIORITY PROJECTS LTD
Facility: NISKU
A#:
Cust. Ref.:
Cust. WO#:

LSD:
Vessel SN:
Valve PO: 092211-7446
Cust AFE#:

Date: 12/07/2022
PSV Location:
Cust Id:
PO LINE#:
Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-17D51V0711 Serial: RVC00022069 Seat: SOFT
Conn. Threaded Inlet: 1" MNPT Orifice: D Outlet: 1" FNPT Vacuum:
Set Press. 125 PSI Back Press.: N/A PSI CDTP: N/A PSI Temp: 70 F Cap: 278 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: 0G8841.5CL7

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 12/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Wally Praxedes

PRETEST 1

[x] Pretest Not Completed Pretest Not Completed Reason: New Valve
Simmer: PSI Set Press: PSI Reseat: PSI Leakage: BPM Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns for ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUGED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS.

DISC: : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Air Simmer: PSI Set Pressure: 125 PSI
Reseat: PSI Leakage Acceptable: [x] B.P. Test: 60 PSI Vacuum: N/A
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge: CDG03/04 Set Press Def: POP
Tested by: Davin Steidel Date Final Tested: 12/08/2022

FINAL INSPECTION:

SEAL: Top: [x] Bottom: [] End Protectors Installed: [x] Painted: [] Palletized: [] Ship Container: [x] Flex Gaskets Supplied: []
Final Inspection: Wally Praxedes Customer Inspection:
Comments: TESTING: LEAK TESTED @90 PERCENT OF SET AS PER API527



7441-B

PRV INSPECTION AND TEST REPORT

BRANCH: Edmonton

UVL ID#: 47779E

Work Order: w14004933-1

Customer PO#: 092211-7446

Customer: PRIORITY PROJECTS LTD
Facility: NISKU
A#:
Cust. Ref.:
Cust. WO#:

LSD:
Vessel SN:
Valve PO: 092211-7446
Cust AFE#:

Date: 10/19/2022
PSV Location:
Cust Id:
PO LINE#:
Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-64K11T86U1 Serial: RVC00021051 Seat: SOFT
Conn. Flanged Inlet: 3" 300 RF Orifice: K Outlet: 4" 150 RF Vacuum:
Set Press. 300 PSI Back Press.: N/A PSI CDTP: N/A PSI Temp: 70 F Cap: 10,720 SCFM
Lift Lever [] Cap Assembly: Closed RFID: Code Symbol: UV CRN#: OG8841.5CL

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve Pretest Required? [x] Reset Required? []

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 10/2022
Seal Condition: Top: Intact Bottom: N/A Insignia: M Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Wally Praxedes

PRETEST 1

Simmer: 0 Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

Table with columns: ITEM, CLEAN, OILY, RUSTY, CARBON, PITTED, CORRODED, SCALE, VIBRATION, GROOVED, DENTED, GALLING, GOUNDED, OTHER, Machined, Lapped, Polished, Replaced, Next Service, Replace, COMMENTS

DISC: : ACT - NOZZLE: ACT - SPRING NUMBER:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Simmer: Set Pressure:
Reseat: Leakage Acceptable: [] B.P. Test: Vacuum:
ADJ. RING SETTING (NOTCHES): Upper: Lower: Test Gauge: Set Press Def: POP
Tested by: Date Final Tested:

FINAL INSPECTION:

SEAL: Top: [] Bottom: [] End Protectors Installed: [] Painted: [] Palletized: [] Ship Container: [] Flex Gaskets Supplied: []
Final Inspection: Customer Inspection:
Comments: